







Instructions / Instrucciones / Mode d'emploi

DL-CD01 Computer Desk


DL-CD01 Escritorio Para Computadora

Do not tighten bolts completely until desk is fully assembled.
 Por favor apretar los tornillos hasta que haya ensamblado el escritorio completamente.







④ x4 / ⑥ x2 / ⑬ x2





⑨ x4 / ⑥ x8 / ⑬ x6 / ⑫ x2





⑩ x2 / ⑧ x1



⑩ x6 / ① x2



⑨ x4 / ⑦ x4 / ⑤ x5




③ x2 / ⑨ x12

The Chart Of Actual Screw Size


⑦




⑧




⑨




⑩



⑪



⑫



⑬

